



RECOMMANDATION : Il est préconisé de remplacer simultanément le relais Y et le condensateur X  
RECOMMENDATION: It's recommended to replace simultaneously both relay Y and capacitor X

<b>Index PDF</b>	<b>Référence</b>	<b>Designation commerciale</b>
A	39919	BASE ASSEMBLY
B	39888	POWER CORD
M	39926	MOTOR
P	39585	BREAKING MODULUS
X	600018S	CAPACITOR 60µF 250V
Y1	500289S	MOTOR RELAY
1	39895	MOTOR SUPPORT ASSEMBLY
2	39896	LOCKING LEVER
3	39897	BOWL CENTRING
4	501010S	SHAFT SEAL
5	39898	BEARING MASK (x2)
6	39899	ON/OFF BLOC ASSEMBLY
7	39900	LEFT BEARING ASSEMBLY
8	507007S	SWITCH
9	39901	RIGHT BEARING ASSEMBLY
10	39902	SHAFT DEFLECTOR
11	39903	MOTOR CENTRING
12	49155	SHAFT PIN
13	39905	BEARING ASSEMBLY
14	39906	BAFFLE
15	118512S	MOTOR FAN
16	39907	MOTOR DEFLECTOR
17	39927	CONTROL PANEL ASSEMBLY
18	39283	PUSHER
19	39909	LID
20	39910	BASKET ASSEMBLY

21	39911	GRATING PLATE
22	39929	ANGLED SPACER
23	39912	FILTER
24	39913	HUB
25	39914	BOWL FLANGE
26	39915	BOWL
27	39916	SPOUT
28	39917	PULP COLLECTOR
29	39928	FEET (X4)
30	39960	SCREWS KIT
31	39516	J100U DIP TRAY
32	49180	RESISTOR SUIT J80/Blixer 2
33	39986	ANTITHEFT TAB J80U KIT
34	49158	KIT SCREWS+NUTS FOR BASKETS J80-J100
35	49226	J80-J100 LONG SPOUT
36	49227	METAL SHEET FOR BIG DRIP TRAY
37	49228	BIG DRIP TRAY
38	49229	FEET FOR ANGLED SUPPORT ASSEMBLY
39	49230	INCLINED BASE J80-J100