




ПЕЧЬ КОНВЕЙЕРНАЯ АРАСН АМТ 40, АМТ 50 С ПОДСТАВКОЙ, АМТ 65 С ПОДСТАВКОЙ, АМТ 80 С ПОДСТАВКОЙ



EXPLOSION DOOR



EXPLOSION SYSTEM



SPARE PARTS LIST

	AMT 40	AMT 50 С ПОДСТАВКОЙ	AMT 65 С ПОДСТАВКОЙ	AMT 80 С ПОДСТАВКОЙ
2	5V010015	5V010015	5V010015	5V010015
3	4P100062	4P100061	4P100061	4P100061
4	/	5M200030	5M200030	5M200030
5	3D010080	3D010080	3D010080	3D010080
6	5V010032	5V010031	5V010031	5V010033
7	4P050102	4P050101	4P050100	4P050103
8	4C020102	4C020101	4C020100	4C020103
9	4P010304	4P010302	4P010300	4P010305
11	5P100052	5P100052	5P100052	5P100052
12	4C041012	4C041021	4C041020	4C041022
15	5R050482	5R050491	5R050490	5R050493
16	5R050483	5R050481	5R050480	5R050493
17	5M020701	5M020701	5M020700	5M020700
18	5V050005	5V050001	5V050001	5V050001
19	5P100301	5P100300	5P100300	5P100300
27	5E200711	5E200706	5E200701	5E200716
28	5S010090	5S010090	5S010090	5S010090
33	5R020122	5R020122	5R020122	5R020122
34	5R020101	5R020101	5R020101	5R020101
35	5T010331	5T010331	5T010331	5T010331
38	5M010100	5M010100	5M010100	5M010100
40	/	4C010402	4C010400	4C010404
42	4P010303	4P010301	4P010300	4P010305
45	5P010500	5P010500	5P010500	5P010500
46	5B100007	5B100007	5B100007	5B100007
47	3G010010	3G010010	3G010010	3G010010
48	5A010115	5A010115	5A010115	5A010115
49	5M100113	5M100113	5M100113	5M100113
50	5M100114	5M100114	5M100114	5M100114
51	5M100115	5M100115	5M100115	5M100115
52	5P100003	5P100003	5P100003	5P100003
53	7N010200	7N010205	7N010210	7N010215